




FIG.4









			 * .				312 pm	
			·] ,	· 			\$0°	
	Start Recording	File: X-487	Urite:			Close		
	\$ \$	88	> Companison	Repaired //S P/S				
	Assure: • Damaged vehicle • Repaired vehicle	Date: 9 Aug 98						
	Measure;	i i	Measurement Method	Damaged D/S P/S				0 11
	Pirk	Clent Mr G. Fellowes	¥		970	1486	troller	
		'	.> 0		970 370	- 1486 e badiy worn	egeneral PC Controller	
	Addio		a <. ⊃ <. =	8	ט ט ט	side front lyn	01010	
	Seject Job:	/dricle: Nesan Maxima	Active Questient.	Dalum Height [203 or Cross Bar	Width Longth Height	Diagonal 210 C 1486		
Do Deta John Holp	Seject (01007	\$ 12	8	S S	> 2 ±	0 8	To the Group	
8			Y					

VEHICL	E M	ŒAS	SUR	EM	ENT	RE	POR	T		
	→	VEHICLE				DATE:				
	RE	0 NO:			JOB:					
		CLIENT:				LE:				
DATUM HEIGHT 203	A	VEH.	ATA	TA DAMAGED			DED			
AT CROSS BAR 203	REF	D/S	P/S	DVS	P/S	D/S	P/S			
WIDTH	G	1200	:	0		0				
LENGTH	С	970	970	-15	. 0	-1	0			
HEIGHT	C	370	370	-7	-1	-1	-1			
DIAGONAL "	С	1486.	1486	-8	٥	-1	0			
COMMENTS: Driver side fro	nt tyre bad	y word.								
	В		DATA	DAM	AGED	REPAIRED				
AT CROSS BAR	REF	D/S	P/S	.D/S	P/S	D/S	P/S			
WIDTH:				1						
LENOTH				 						
HEIGHT										
DIAGONAL								1		
COMMENTS:										
	C	1000	5.7.	1500				1		
DATUM HEIGHT			DATA			 		}		
AT CROSS BAR	REF	D/S	P/S	D/S	P/S	D/S	P/S			
LENGTH		 	 	 	 		}	{		
HEIGHT	 	-			 			1		
DIAGONAL		 	 	-		 		-		
	<u></u>		<u> </u>	<u> </u>	<u> </u>	1	<u> </u>	<u> </u>		
COMMENTS:	-									
DATUM HEIGHT	D	D VEH.D		ATA DAMAGED		REPAIRED]		
AT CROSS BAR	REF	D/S	P/S	D/S	P/S	D/S	P/S]		
WIDTH	_ ^	1478		0		0]		
LENGTH	В	844	844	-22	0	0	0]		
HEIOHT	С			89	89	89	89]		
DIAGONAL	D	1662	1662	-11	0	-1	0	ا		
COMMENTS:										
Operator:										
Signed:										
			4	7						

<u>FIG.9</u>